



















ASSEMBLE INSTRUCTION 7037H

<p>Ax1</p> 	<p>Bx5</p> 	<p>Cx1</p> 	<p>Dx1</p> 
<p>Ex2</p> 	<p>Fx1</p> 	<p>Gx1</p> 	<p>Hx1</p> 
<p>Ix1</p> 	<p>Jx1</p> 	<p>Kx1</p> 	<p>Lx1</p> 
<p>Mx8</p> <p>M8*20mm</p> 	<p>Nx4</p> <p>M8*25mm</p> 	<p>Rx4</p> <p>M5*12mm</p> 	<p>Ox12</p>  <p>Px1</p>  <p>Qx4</p> 

ASSEMBLE INSTRUCTION 7037H

